

RECENT RECALLS

Vehicle	Year	Description of Recall
<p>MERCEDES BENZ METRIS</p>	<p>2016-2017</p>	<p><b>NHTSA Campaign Number:</b> 18V837000</p> <p><b>Manufacturer</b> Daimler Vans USA, LLC</p> <p><b>Components</b> FUEL SYSTEM, GASOLINE</p> <p><b>Summary</b></p> <p>Daimler Vans USA, LLC (DVUSA) is recalling certain 2016-2017 Mercedes-Benz Metris vehicles. The fuel hose in the engine compartment may leak at the lower connecting point of the transition hose, between the underbody fuel line and the Schrader valve and/or where the fuel line connects to the fuel pump.</p> <p><b>Remedy</b></p> <p>DVUSA will notify owners, and dealers will replace the affected hose and clamp, free of charge. <b>The recall is expected to begin January 25, 2019.</b> Owners may contact DVUSA customer service at 1-877-762-8267.</p>
<p>MERCEDES BENZ GLC300</p>	<p>2019</p>	<p><b>NHTSA Campaign Number:</b> 18V840000</p> <p><b>Manufacturer</b> Mercedes-Benz USA, LLC.</p> <p><b>Components</b> STEERING</p> <p><b>Summary</b></p> <p>Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2019 GLC300 vehicles. An internal sensor within the electric power steering unit may fail, deactivating the power steering assist.</p> <p><b>Remedy</b></p> <p>MBUSA will notify owners, and dealers will replace the steering unit, free of charge. <b>An interim letter will be mailed beginning January 25, 2019 to notify owners of the issue. A second letter will be mailed once remedy parts are available.</b> Owners may contact MBUSA customer service at 1-800-367-6372.</p>

<p>PORSCHE</p>	<p>PANAMERA</p>	<p>2018</p>	<p><b>NHTSA Campaign Number:</b> 18V841000</p> <p><b>Manufacturer</b> Porsche Cars North America, Inc.</p> <p><b>Components</b> SERVICE BRAKES, HYDRAULIC</p> <p><b>Summary</b></p> <p>Porsche Cars North America, Inc. (Porsche) is recalling certain 2018 Porsche Panamera Turbo S Hybrid Executive, Panamera 4 Hybrid, Panamera Turbo S Hybrid, Panamera 4 Hybrid Executive, Panamera 4 Hybrid Sport Turismo, and Panamera Turbo S Hybrid Sport Turismo vehicles. The brake lines installed on the front axle may corrode over time. Corrosion inside the line may affect the front braking performance.</p> <p><b>Remedy</b></p> <p>Porsche will notify owners, and dealers will replace the brake line, and any damaged brake components, free of charge. <b>The recall is expected to begin January 27, 2019.</b> Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is AJ11.</p>
----------------	-----------------	-------------	--

<p>HONDA PILOT HONDA RIDGELINE</p>	<p>2019 2019</p>	<p><b>NHTSA Campaign Number:</b> 18V848000</p> <p><b>Manufacturer</b> Honda (American Honda Motor Co.)</p> <p><b>Components</b> STRUCTURE</p> <p><b>Summary</b></p> <p>Honda (American Honda Motor Co.) is recalling certain 2019 Honda Ridgeline and Pilot vehicles. The mounting holes for the clip that secures the right center pillar trim panel may be larger than intended. In the event of a crash necessitating right side curtain air bag deployment, the clip may not hold the center pillar trim panel in position and it may potentially interfere with the curtain air bag deployment. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 214, "Side Impact Protection," and 226, "Ejection Mitigation."</p> <p><b>Remedy</b></p> <p>Honda will notify owners, and dealers will install a bracket on the right center pillar that will securely hold the center pillar trim clip, free of charge. <b>The recall is expected to begin January 25, 2019.</b> Owners may contact Honda customer service at 1-888-234-2138. Honda's number for this recall is D3D.</p>
<p>MERCEDES BENZ E450 MERCEDES BENZ E63S AMG</p>	<p>2019 2019</p>	<p><b>NHTSA Campaign Number:</b> 18V849000</p> <p><b>Manufacturer</b> Mercedes-Benz USA, LLC.</p> <p><b>Components</b> STRUCTURE</p> <p><b>Summary</b></p> <p>Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2019 Mercedes-Benz E450 4Matic Wagon and E63S AMG Wagon vehicles. The affected vehicles have a tailgate mounted spoiler that may not be properly attached and therefore could detach while driving.</p> <p><b>Remedy</b></p> <p>MBUSA will notify owners, and dealers will inspect and correct the mounting of the spoiler, as necessary, free of charge. <b>The recall is expected to begin December 19, 2018.</b> Owners may contact MBUSA customer service at 1-800-367-6372.</p>



SafeCar.Gov Recall Lookup. <https://vinrcl.safercar.gov/vin/>